

# HANWA ENGINEERING CO, LTD.

3RD FLOOR. JPC BLDG. 7-22, UTSUBOHONMACHI, 1-CHOME, NISHI-KU, OSAKA, JAPAN.  
TEL: 816 6444 7830 FAX: 816 6444 7831

## SERVICE REPORT

VESSELS NAME :  
PLACE OF WORK : WEIHAI CHINA

DATE : 2020/5/28—2020/5/31  
REF. NO :

DESCRIPTION		REMARKS
<p>Boarded the vessel for elevator annual inspection.</p> <ol style="list-style-type: none"><li>1. Main motor. brake system checked &amp; found normal</li><li>2. Main wire ropes checked &amp; found normal.</li><li>3. Travelling cables checked &amp; found normal.</li><li>4. All doors' interlocks, speedgovernors tested &amp; found normal.</li><li>5. The distance between the counterweight and the safety buffer is "450mm", within the safety scope.</li><li>6. All safety devices, limit switches tested &amp; found normal.</li><li>7. 0%. 100%. 125%. load test.</li></ol>		

