



HANWA ENGINEERING CO., LTD.

9F, URBAN RESEARCH BLDG. 1-6-4, KYOMACHIBORI
NISHI-KU, OSAKA, JAPAN

TEL: 816-6444-7830 FAX: 816-6444-7831

E-MAIL: operation@hanwaeng.co.jp

voucher

VESSEL NAME:	DATE 5TH JULY.2020
PLACE OF WORK: NANTONG PORT	REF. NO:

WE ARRANGE FOLLOWING WORKS TO SUBJECT SHIP AT NANTONG PORT

SUBJECT: FOR BOILER INSPECTION

1. Boiler valve overhauling including safety valve
Valves bring to workshop, cleaning, lapping, replace packing and gasket as necessary
9pcs; two safety valve re-adjust pressure and popping test on board in front of surveyor
2. Smoke side manhole 3pcs & water side manhole 2pcs open; cleaning inside, close with new gaskets
3. Supply gasket 3mm thickness 1 sheet
4. Boiler gauge was calibrated and deliver the report to ship

Necessary local transportation 2 lots

Boarding pass for 3 workers

